

# Heathrigg Nursery Asbestos Management Plan

Review Date: March 2014

Asbestos insulation board has been identified within the switch room. All maintenance and refurbishment activities requiring work on this material **must be carried out by a licensed asbestos removal contractor.** 

Vinyl flooring and textured coated ceilings have also been identified with an asbestos content in some areas of the building. Areas of Asbestos found are shown on the attached plans with references to the Asbestos Management Survey to provide more detailed information on the location of the asbestos materials. Removal of these asbestos materials can be carried out by a competent contractor as non licensed work.

A targeted Refurbishment Survey will be required prior to any work being carried out if not specifically shown on the Plans. Development Services Construction Support must be notified of any work on asbestos containing material or for advice on whether removal will be required – Tel 01324 504905 or email - asbestosdevserv@falkirk.gov.uk)

All works to be carried out in Heathrigg Nursery will be subject to a Permit to Work System.

#### **PERMIT TO WORK**

A permit to work in is required for all works carried out on the fabric of the building including survey work. The permit will confirm that contractor's employees have been notified of the presence of asbestos and are aware of the restrictions imposed.

All tradesmen (including Council employees) will be required to sign in at reception and complete the permit to work.

Works involving planned work to areas identified as containing Asbestos will require the contractors to submit a completed permit to work form for approval, with all relevant documentation, to Development Services, Roads & Design, Construction Support at least 48 hrs prior to the planned start date.

Contractors working out of hours on emergency work will be required to notify the Nursery Management & Development Services Construction Support as soon as possible after accessing the building with details of the works carried out.

A copy of all permits issued will be recorded and retained by the school management.

#### Documents attached:

Appendix 1. Risk assessment.

Appendix 2. Permit to work Pro-forma.

Appendix 3. Location plans for asbestos material -

# Appendix 1

# Priority Risk Assessment of Known Asbestos Materials (See table 1 Algorithm attached (average per section))

Sample No	Room No	Occupant Activity (MAX 6)	Likelihood of disturbance (MAX 9)	Human exposure potential (MAX 9)	Maintenance activity (MAX 6)	Material risk assessment (MAX 12)	Total Score (MAX 24)	Action Required
006 Residue to joists	012	0	1	1	0	11	13 Med	Monitor. Work on this material will require a plan of work to be submitted to Development Services,
005 insulating board		0	1	1	0	5	7 Low	Construction support for approval.  Care to be taken to avoid damage to this material – All work to be carried out by a licensed asbestos removal contractor.
004 Vinyl tiles	012 & 015	0	1	1	0	3	5 low	Monitor and remove if work requires it.
001, 003, 007, 009, 011, 013, 015, 016. textured coatings	005, 011, 013, 014, 016, 017, 019, 020, 021, 022, 024, 025, 027, 029.	1	2	2	1	2	8 Low	Monitor and remove if work requires it.

# Appendix 2



## Heathrigg Nursery, Slamannan

Permit No Date

## PERMIT TO WORK

HAZARD: Asbestos materials are located as shown on attached plans and asbestos survey.

Contractor Name,			
Address			
Telephone Number	Email add	ress	
Description of work: attach o	opies of the work order	or project drawings.	
`			
		The second secon	100 100 100 100 100 100 100 100 100 100
			STORMAN STATE OF THE STATE OF T
Is work required on the asbest attached location plans? YE (If YES refuse access unless t person authorising the works)	S / NO he documents below hav		
Documents Required		Documents Supplied	Checked By
Method state	ements	Yes ( ) No ( )	
Risk Assessi	ments	Yes ( ) No ( )	
Medical Cert	ificates	Yes ( ) No ( )	
Training Re	cords	Yes ( ) No ( )	
Asbestos Contractor Check I Construction S		Yes ( ) No ( )	
		IF <b>NO</b> REFUSE PERMIT	E
	Signature:		Date:
I have read and understood this permit and will undertake work accordance with the conditions	in	, i	er e e e e e e e e e e e e e e e e e e
Permit issued by:	Signature:		Date
Work Completed:	Signature:	;	Date

### HAZARDS IDENTIFIED:

Textured coating, to ceilings beams and columns have been identified as asbestos insulation

Provide List of Employees, including signature, showing that they have been notified of the above HAZARD [see over]

### LIST OF EMPLOYEES

NAME	SIGNATURI	E	I	)ATE
	***************************************		27.6° 10.00 27.6° 10.00 27.6° 10.00	
•		. A		
			=	
			100 100 100 100 100 100 100 100 100 100	
		**		4. k
			1,000 (10,000) 10,000	90. 975. 555.
			**************************************	
		V	The second secon	
	***	Andrews Company of the Company of th	Y comment of the comm	
		TO A CONTROL OF THE STATE OF TH	2. Targette	C
		200 200 200 200 200 200 200 200 200 200	100 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	
**************************************				

## ASBESTOS CONTRACTOR CHECKLIST

Address:							
Date:							
Contractor:							
H.S.E Licence	YES	NO	Licence No.:	Licence No.:			
Asbestos Work							
H.S.E. Notification	YES	NO	Number:				
Risk Assessment/Me	thod Statement:	YES NO	Suitable/Sufficient	YES NO			
Plant Testing:	Plant Type:	-	Serial Numbers:				
			10 to	<u></u>			
			1				
DCU	Clearance Certificate		YES	NO			
			**************************************	·.			
	Negative Pressure Ur	nit (DOP test	YES	NO			
	certificate)		Transmission and a second seco	The state of the s			
		Company of the Compan	The second secon				
Training Records	ning Records Name:			NO			
		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	**************************************				
		**************************************					
			mineman, Service Control of the Cont				
	######################################	(1) (1) (1) (1) (1) (1) (1) (1) (1) (1)	100 100 100 100 100 100 100 100 100 100				
Face Fit Test	Name:	300 000 000 000 000 000 000 000 000 000	YES	NO			
Results	19.1 September 19.2 S		,				
		**************************************					
	200 (100 (100 (100 (100 (100 (100 (100 (		2 00 00 00 00 00 00 00 00 00 00 00 00 00				
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	The second secon	-				
Part .	101	Total Control   Control Cont					
Medical Records	Name:	**************************************	YES	NO			
	**************************************						
	To the second se						
The state of the s		manufacture and a second and a					
200 200 200 200 200 200 200 200 200 200	**************************************						
Falkirk Council	YES	NO	Number:	<u> </u>			
Order							
Contractor's Order	YES	NO	Number:				
	7 100 100 100 100 100 100 100 100 100 10						
Comments:			<u></u>				
	Port of the second seco						
			,	***************************************			

# Appendix 3

-

•

-

