

## Energy performance certificate (EPC) recommendation report

UNIT 6 Spectrum House 32-34 Gordon House Road LONDON NW5 1LP	Report number <b>9626-4037-0166-0208-9271</b>
	Valid until <b>12 May 2026</b>

---

### Energy rating and EPC

This property's current energy rating is E.

For more information on the property's energy performance, see the EPC for this property.

---

## Recommendations

Make these changes to improve the property's energy efficiency.

Recommended improvements are grouped by the estimated time it would take for the change to pay for itself. The assessor may also make additional recommendations.

Each recommendation is marked as low, medium or high. This shows the potential impact of the change on reducing the property's carbon emissions.

### Changes that pay for themselves within 3 years

Recommendation	Potential impact
Consider replacing T8 lamps with retrofit T5 conversion kit.	High

### Changes that pay for themselves within 3 to 7 years

Recommendation	Potential impact
Add optimum start/stop to the heating system.	Medium

### Changes that pay for themselves in more than 7 years

Recommendation	Potential impact
Some walls have uninsulated cavities - introduce cavity wall insulation.	Medium
Some windows have high U-values - consider installing secondary glazing.	Medium
Add weather compensation controls to heating system.	Medium
Carry out a pressure test, identify and treat identified air leakage. Enter result in EPC calculation.	Medium
Consider installing building mounted wind turbine(s).	Low

## Property and report details

Report issued on	13 May 2016
Total useful floor area	237 square metres
Building environment	Heating and Natural Ventilation
Calculation tool	CLG, iSBEM, v5.2.g, SBEM, v5.2.g.3

## Assessor's details

Assessor's name	James Penrose
Telephone	07917198526
Email	<a href="mailto:jamesp-1983@live.com">jamesp-1983@live.com</a>
Employer's name	Carbon Profile Ltd
Employer's address	Unit 2 Long Leys Farm, Leys Road, Oxford, OX2 9QG
Assessor ID	STER000520
Assessor's declaration	The assessor is not related to the owner of the property.
Accreditation scheme	Sterling Accreditation Ltd